## Oil Field Environmental Incident Summary

**Incident:** 20160211180649 **Date/Time of Notice:** 02/11/2016 18:06

**Responsible Party:** CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: BOHMBACH 1-35H

Field Name: ELM TREE Well File #: 18137

Date Incident:2/10/2016Time Incident:20:00Facility ID Number:County:MCKENZIETwp:153Rng:94Sec:35Qtr:

**Location Description:** 

Submitted By: Todd Senescall Received By:

Contact Person: Travis Simnioniw

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

0.5 Barrels 25.5 barrels

Oil 0.5 B

Brine Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 4/5/2016 Clean Up Concluded: 3/1/2016

Risk Evaluation:

explosion

Areal Extent:

An area approximately 80' X 40' on location and outside of the containment dike was misted by oil.

## Potential Environmental Impacts:

soil

## Action Taken or Planned:

Fire extinguished. Snowfall after the fire has delayed any recovery of contaminated material. no standing fluid to recover. Boom was installed downhill of the misted area to prevent any oil release from location during snow melt. Incident investigation continues.

Wastes Disposal Location: TBD, likely Secure Energy

Agencies Involved: Local Fire Department

## **Updates**

Date: 2/12/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release, due to a fire, remained on facility site according to the report. NDIC retains oversight.